

Entergy Nuclear Northeast Entergy Nuclear Operations, Inc. Indian Point 3 NPP P.O. Box 308 Buchanan, NY 10511 Tel 914 736 8001 Fax 736 8012

Robert J. Barrett Vice President, Operations-IP3

July 9, 2001 IPN-01-052

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Stop O-P1-17 Washington, DC 20555-0001

SUBJECT:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286 License No. DPR-64

10 CFR 21 Interim Report

Failure During Post Installation Testing of Replacement Governor Manufactured

by Woodward Governor and Refurbished by Engine Systems, Inc.

Dear Sir:

The attached Interim Report is being submitted in accordance with 10 CFR 21(a)(2) to address a potentially reportable equipment failure. A replacement governor installed on the 32 Emergency Diesel Generator failed during post installation testing. The governor has been returned to Engine Systems Inc. for failure analysis to determine if there is a deviation that would make the failure a reportable defect.

Indian Point 3 is not making any new commitments associated with this letter. If you have any questions regarding this submittal, please contact Mr. J. Donnelly.

Very truly yours,

Robert J. Barrett Vice President Operations

Indian Point 3 Nuclear Plant

cc: see next page

75/9

Docket No. 50-286 IPN-01-052 Page 2 of 2

CC:

Mr. Hubert J. Miller Regional Administrator Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Resident Inspector's Office Indian Point Unit 3 U.S. Nuclear Regulatory Commission P.O. Box 337 Buchanan, NY 10511

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

Attachment 1 Docket No. 50-286 IPN-01-052 Page 1 of 2

## Interim 10 CFR 21 Report

### 1. Name and Address

Mr. Robert J. Barrett - Vice President, Operations Entergy Nuclear Operations, Inc. Indian Point 3 Nuclear Power Plant P.O. Box 308 Buchanan, N.Y. 10511

## 2. Facility, Activity or Component

Indian Point 3 Nuclear Power Plant (IP3)

The component was a Woodward Governor Part No. 9903-152, type EGB-13C, Serial No. 1165395.

The governor was supplied refurbished to the Public Service Electric and Gas (PSE&G) Salem Station by Engine Systems, Inc. under purchase order P3 0934734 1180 0000. IP3 subsequently purchased the governor from Salem Station.

## Constructor or Supplier

Engine Systems, Inc. 1220 S. Washington St. Rocky Mount, NC 27801

## 4. Defect and Safety Hazard

A replacement governor was installed in the 32 Emergency Diesel Generator (EDG) during the EDG eight year preventive maintenance (PM). On May 11, 2001, the governor worked satisfactorily during initial start, set up and compression checks at 1,750 KW following the eight year PM. During the May 11, 2001, 8 hour surveillance run at 1,950 KW the governor began to oscillate between 1,950 and 1,850 KW and was unstable. The load was reduced and the engine shut down. Troubleshooting did not identify the failure mechanism. The governor was removed from the EDG and returned to Engine Systems, Inc. for failure evaluation on May 30, 2001.

The governor is used to control the EDG and failure would be expected to affect the ability of the 32 EDG to provide emergency electrical power when called upon. This could have caused the failure of safety related systems under certain postulated accidents with a loss of offsite power. Therefore, a substantial safety hazard existed in that the potential existed for a significant degradation of essential safety related equipment.

#### 5. Date

The failure was discovered May 11, 2001. A 10 CFR 21 report by Engine Systems, Inc. dated March 6, 2001, reported a generic defect in a number of Woodward

Attachment 1 Docket No. 50-286 IPN-01-052 Page 2of 2

# Interim 10 CFR 21 Report

governors worked on by a single individual. The governor installed at IP3 was not one of the seven identified in the Part 21 report as one of concern. An evaluation under 10 CFR 21 was initiated on May 21, 2001.

6. Location and Number of Defective Components

This condition was limited to the governor installed on 32 EDG.

7. Corrective Action

The original governor, removed for scheduled preventive maintenance, was reinstalled and tested.